






END-TO-END CUSTOMER PORTAL

Overview of Map Update Procedure

Step	Item	Outline
Step ①		<p>Prepare USB storage drive to copy the new map data for the update.</p> <p>(Europe ISA map requires 5GB. Europe Embedded Map requires 25GB)</p> <p>Note: You may require a conversion cable depending on your vehicle and your USB storage drive. For example, Suzuki Swace is equipped with USB Type C ports alone. You will require a USB Type C to USB Type A conversion cable if your USB storage drive is Type A.</p> <p>The USB requirements are as below.</p> <ul style="list-style-type: none"> ● Capacity: 32GB ● Format: FAT32
Step ②		<p>Check “Map Update ID” and “Map Service Code”.</p> <ul style="list-style-type: none"> ● The “Map Update ID” is a 16-digit number that is unique to each navigation system. ● The “Map Update ID” can be checked on the screen of the navigation system. <ul style="list-style-type: none"> ➢ If “Map Update ID” = xxxx-1xxx-xxxx-xxxx then only select the 20GB map type ➢ If “Map Update ID” = xxxx-2xxx-xxxx-xxxx then only select the 5GB map type ● Please do not include hyphens in the information you input into the portal. ● Each information is necessary to obtain a “License Key Number”.

<p>Step ③</p>	<p>License Key No.</p> 	<p>PC is used to access the https://www.suzuki-isa-map-update.com/ portal via the internet.</p> <p>Choose desired map to download map data to USB and input “Map Update ID” and “Map Service Code”. “License Key Number” will be generated and make sure to record the “License Key” number shown on the screen. Click “Download Map File” to start map download.</p>
<p>Step ④</p>	 <p>License Key No.</p> 	<p>Insert USB storage drive, input “License Key Number” and Map update will start.</p>




PART 1: PREPARE REQUIRED INFORMATION


This step is completed using the multimedia system of your Suzuki vehicle.

How to retrieve Map Update ID


1. Select “Navigation”.



2. Select “Map update”.



3. Select “Map data info” and check “Map update ID”.




- Make a note of the “Map update ID” as this will be required for Part 2. If “Map Update ID” = xxxx-1xxx-xxxx-xxxx then only select and download the 20GB map type. If “Map Update ID” = xxxx-2xxx-xxxx-xxxx then only select and download the 5GB map type.

How to retrieve Map Service Code


1. Select "Navigation".



2. Select "Map update".



3. In the displayed map data screen, check "Map service code".



! The last digit of the service code indicates the map updating method which should be used. Check the last digit is "M" for the free period (M: Free method, Y: Paid method).

PART 2: DOWNLOAD UPDATE & PREPARE USB

This step is completed using the Suzuki ISA Map Update Portal for Non-connected Vehicles and the information you acquired from your Suzuki vehicle at **Part 1**.

1. Navigate to Suzuki ISA Map Update Portal for Non-connected Vehicles at <https://www.suzuki-isa-map-update.com/>




Figure 1: Landing page of Suzuki ISA Map Update Portal for Non-connected vehicles

2. Scroll down to the section titled “Select your map type”
3. Choose the map type suitable for your vehicle and click “Download file”
 - ~5 GB ISA update file if the 5th (fifth) digit of your Map Update ID is 2 (left one in below image)



- ~20 GB ISA update file if the 5th (fifth) digit of your Map Update ID is 1 (right one in below image)



Figure 2: Clicking “Download file” buttons will open a popup screen for downloading your map update

4. Input the information you acquired from your Suzuki vehicle at **Part 1**
 1. Input “Map Update ID” to the input field labelled as “**Map Update ID**” (*do not include hyphens*)
 2. Input “Map Service Code” to the input field labelled as “**Map Service Code**”

×

Europe 25-1, Swace 5G V1
Last updated: 2025-08-06

Map Update ID *
e.g. 1234567890123456

Map Service Code *
e.g. 210248939

CANCEL

GENERATE LICENCE KEY

Figure 3: Initial input screen with empty fields

×

Europe 25-1,Swace 5G V1
Last updated: 2025-08-06

Map Update ID *
1234567890123456 ✓

Map Service Code *
123456 ✓

CANCEL

GENERATE LICENCE KEY

Figure 4: After inputting the information received at Part 1

×

Europe 25-1,Swace 5G V1
Last updated: 2025-08-06

Map Update ID *
123456789012345

Map Service Code *
123456 ✓

CANCEL

GENERATE LICENCE KEY

Figure 5: You will not be able to generate a licence key in case an invalid input is provided. In above case, an invalid map update id is provided. Make sure you input the correct information received at Part 1.

5. Click “Generate Licence Key”.



! SUCCESSFUL LICENSE KEY GENERATION

- The portal will generate a new “License Key” successfully.
- Please copy your “License Key”, either by:
 - Copying to clipboard
 - Selecting your license key, right clicking, and clicking “Copy”, or using the designated shortcut command such as Control+C or Command-C
 - Clicking the “Copy” button
 - Physically writing it down

*You will need your “License Key” during the next step. Make sure you have access to it until you complete **Part 3**.*

×

Europe 25-1,Swace 5G V1
Last updated: 2025-08-29

✓

 Licence Key generated successfully!

Licence Key

Copy

i

 Copy the Licence key or write it down, you will need it later!

Instructions for next steps

1. **MacOS Devices:** Download and unzip the map update file, “MAPUPDATE” folder, and copy all its contents to a USB drive.

2. **Windows OS Devices:** Download and unzip the map update file, then locate the sub folder named “MAPUPDATE” and copy all its contents to a USB drive.

3. Plug the USB drive into your vehicle's designated ISA map update port.

4. When prompted, follow the on-screen instructions and enter the provided license key.


CANCEL

DOWNLOAD MAP FILE

Figure 6: Successful license key generation

⚠️ UNSUCCESSFUL LICENSE KEY GENERATION

- The portal will display an error message.
- There can be several reasons, including:
 - Incorrect **“Map Update Id”** or **“Map Service Code”**
 - Please confirm you received the correct information at **Part 1**.
 - Your vehicle is not eligible for the map type you have chosen.
 - Please confirm you selected the **“Map Type”** applicable for your Suzuki vehicle.
 - Your vehicle is not eligible for a free map update.
 - Please contact your preferred **Suzuki dealer** regarding free map update eligibility.
 - Network connection related issues.
 - Please ensure your **network environment** is working as expected and not blocking anything which might keep the portal from working as expected.
 - Portal or server related issues.
 - Please contact your preferred **Suzuki dealer**.



The screenshot shows a web portal window titled "Europe 25-1,Swace 5G V1" with a close button (X) in the top right corner. Below the title, it says "Last updated: 2025-08-06". A red error banner with a white exclamation mark icon contains the text "Incorrect map update id or map service code". Below this, there are two input fields. The first is labeled "Map Update ID *" and contains the text "1234567890123456" with a green checkmark icon to its right. The second is labeled "Map Service Code *" and contains the text "123456" with a green checkmark icon to its right. At the bottom of the form, there are two buttons: a white "CANCEL" button and a blue "GENERATE LICENCE KEY" button.

Figure 7: Unsuccessful licence key generation



6. You can now click “Download Map File” button to start downloading your map update file.

Europe 25-1, Swace 5G V1 ×

Last updated: 2025-08-29

✓ Licence Key generated successfully!

Licence Key

Copy

ⓘ Copy the Licence key or write it down, you will need it later!

Instructions for next steps

1. **MacOS Devices:** Download and unzip the map update file, “**MAPUPDATE**” folder, and copy all its contents to a USB drive.
2. **Windows OS Devices:** Download and unzip the map update file, then locate the sub folder named “**MAPUPDATE**” and copy all its contents to a USB drive.
3. Plug the USB drive into your vehicle's designated ISA map update port.
4. When prompted, follow the on-screen instructions and enter the provided license key.

CANCEL DOWNLOAD MAP FILE

Figure 8: Download the map update file, which is served as a single ZIP file.

7. After the download has been completed, insert the **USB storage device** into the USB port of your device.

Please make sure your device has an adequate amount of empty space available depending on your map type. We recommend an empty USB storage device with:

1. Empty storage formatted as **FAT32**
2. **32GB** of memory

⚠ You may require an adapter depending on the compatibility of your device's USB connector and the port of your Suzuki vehicle.

8. **Unzip** the map update file you have downloaded at **Step 6** and follow **either Step 9 OR Step 10** depending on your device operating system.
9. **MacOS Devices:** **Copy** the unzipped map update file, “**MAPUPDATE**” folder, and all its contents directly to the **USB storage device**.




Figure 9: Example of downloaded zipped map update file on MacOS device.




Figure 10: Example of unzipped map update file on MacOS device; “MAPUPDATE” folder as a top-level folder.

10. **Windows OS Devices:** When the map update file is unzipped, Windows OS will create a top-level folder matching the Zip file name, **open the top-level folder** and locate the **sub folder** named “**MAPUPDATE**”, then **copy the MAPUPDATE folder** and all its contents directly to the **USB storage device**.




Figure 11: Example of downloaded zipped map update file on Windows OS device.




Figure 12: Example of unzipped map update file on Windows OS device; “MAPUPDATE” folder as a sub folder.


11. **Unplug** the USB storage device once copy is complete.




PART 3: INSTALL MAP UPDATE IN VEHICLE

This step is completed using the USB drive which contains the map update file and the license key you acquired from Suzuki ISA Map Update Portal for Non-connected Vehicles at **Part 2**, and the multimedia system of your Suzuki vehicle.


Firmly depress the brake pedal and then press the POWER button, the below READY indicator is then displayed.



1. Select the settings icon and select “Navigation”.




2. Select “Map update”.







3. Connect the USB storage device which contains the unzipped map update file and select "Update".



4. Select "Yes" to transition to a screen where the version can be confirmed.





5. Enter the license key number.






- *When installing the latest version:*

Select “Yes” when a notification indicating that a software update is necessary is displayed.




6. Turn off your vehicle by pressing the POWER button
7. Turn on your vehicle by firmly depressing the brake pedal and then pressing the POWER button once more.
8. ISA map update starts.
9. Wait until the map update has been completed.





10. After the map update has been completed, turn the ignition switch off by pressing the POWER button and then to Adaptive Cruise Control (ACC).



⚠ When the latest version has already been installed:

Turn the ignition switch off by pressing the POWER button and then to Adaptive Cruise Control (ACC) after the following screen is displayed.




11. After startup, select the map button and wait until the screen transitions to the below screen.

⚠ When installing the latest version:

When the following screen is displayed, select "OK".

Do not remove the USB storage device until the map update has completed.



12. Select “OK” and disconnect the USB storage device.

